

The background of the entire page is a close-up, high-resolution photograph of water ripples. The ripples create a complex, organic pattern of light and dark blue-green tones, with some areas appearing more saturated than others. The lighting creates highlights and shadows that emphasize the texture of the water's surface.

# **OUTDOOR POOL FILTRATION CASE**





## Long Service Lifetime with Superior Water Quality

### The Case

**Location:** Allerød, Denmark

**Pool Type:** Outdoor pool

**Size:** 18 x 7 m + A small children's pool

**Details:** A privately owned outdoor pool for a local community. Open three months a year.

**Commissioning:** 2010

In Allerød, a local community near Copenhagen, Denmark, most young people spend their summer school vacations by Rønneholtparken's pool, swimming, playing, and having fun. Elderly residents enjoy morning swims, and water-loving families use their sunny weekends in the cozy pool area.

For the community to enjoy this pool area, it is essential for the daily operation team, John and Jan, that the pool is safe and the water quality is living up to the standards and regulations. That is why they chose the LiqTech Pool Filtration System for cleaning the pool water back in 2010. John and Jan are taking good care of the elderly LiqTech Pool Filtration System, and the system has been running without replacing the membranes during the 13 years of operation.

”

We are very fulfilled with the LiqTech pool filtration system.

**John**

Operation, Rønneholtparken

## The Solution

**This filtrations system has been cleaning the pool water for over a decade, three to four months yearly. The pool is like most outdoor pools, exposed to high concentrations of oils from sunscreen, bacteria, and other unwanted particles from the users of the pool, as well as dirt, leaves, and other organic matter from the outdoor environment.**

As pre-treatment to the LiqTech Filtration System, the operation has a simple strainer (1,000 micron) conducting hair, leaves, and other debris. Backwash is performed 1 – 2 times daily in the operations period, and the chemical membrane cleaning (CIP) is performed three times a month during the three months in the summer period when the pool is open.

# Excellent water quality

Excellent water quality is documented by the weekly lab analysis in Rønneholtparken.

## AUTHORITY REQUIREMENTS (DK)

## LIQTECH SYSTEM

Parameter	Unit	Quality Requirement		
		Minimum	Maximum	
Clearness		The water must be clear		OK
pH		6,8	7,6	OK
Free Chlorine	mg/l	1	2	OK
Total Chlorine	mg/l		0,5	OK
Trihalomethaner (THM)	µg/l		50	OK

## We are here to help you



### Parisha Zarmeen Brinch

Area Sales Manager  
Phone: +45 5159 5106  
pzb@liqtech.com

### LiqTech

Phone: +45 4498 6000  
info@liqtech.com  
<https://liqtech.com/>